



Photo P324. Feature MA\_TM\_432. Vegetated swale in the center of the image, access road in the foreground. Looking East, in Malheur County. 4/29/2013 10:11. Latitude 44.111768. Longitude -117.208615.



Photo P325. Feature MA\_TM\_431. Swale now used as a trail can be seen on either side of the access road. Looking SE, in Malheur County. 4/29/2013 9:59. Latitude 44.109813. Longitude -117.216273.



Photo P326. Feature MA\_TM\_466. Upland swale with no signs of water influence. Russian thistle in bottom of swale. Looking West, in Malheur County. 6/13/2013 8:39. Latitude 44.100628. Longitude -117.205499.



Photo P327. Feature MA\_TM\_427. Ephemeral channel in the center on the image with sediment deposits in channel. Looking SE, in Malheur County. 4/29/2013 8:46. Latitude 44.109076. Longitude -117.233024.





Photo P328. Feature MA\_TM\_428. Access road to the left and temporarily ponded area with old tire tracks in the center. Looking East, in Malheur County. 4/29/2013 9:16. Latitude 44.109363. Longitude -117.233629.



Photo P329. Feature MA\_TM\_429. Temporarily ponded area adjacent to road. No hydric soil or wetland vegetation indicators. Looking South, in Malheur County. 4/29/2013 9:20. Latitude 44.109438. Longitude -117.23451.



Photo P330. Feature MA\_TM\_472. Upland valley bottom with no signs of water influence in NWI mapped R4. Looking SE, in Malheur County. 6/13/2013 9:56. Latitude 44.090533. Longitude -117.230246.



Photo P331. Feature MA\_TM\_475. Dry valley bottom with no channel indicators, livestock in the background. Looking South, in Malheur County. 6/13/2013 10:30. Latitude 44.08619. Longitude -117.244639.





Photo P332. Feature MA\_TM\_481. Canal with dense *Lepidium* along bank. Looking West, in Malheur County. 6/14/2013 7:59. Latitude 44.076246. Longitude -117.285267.



Photo P333. Feature MA\_TM\_482. Irrigation canal running adjacent to a gravel access road. Looking North, in Malheur County. 6/14/2013 8:07. Latitude 44.076409. Longitude -117.285293.



Photo P334. Feature MA\_TM\_483. Irrigation ditch with a cement control structure in the center of the image. Looking East, in Malheur County. 6/14/2013 8:24. Latitude 44.076207. Longitude -117.28519.



Photo P335. Feature MA\_TM\_465. Cement spillway in the center of the image with the paved road to the right. Looking West, in Malheur County. 6/12/2013 11:04. Latitude 44.068933. Longitude -117.309946.





Photo P336. Feature MA\_TM\_460. Wetland to the left of the yellow GPS unit and upland to the right. Looking NE, in Malheur County. 6/11/2013 12:50. Latitude 44.065308. Longitude -117.315484.



Photo P337. Feature MA\_TM\_459. Shovel marks upland plot in area with whitetop and rose, no wetland indicators. Looking SW, in Malheur County. 6/11/2013 10:41. Latitude 44.062566. Longitude -117.316686.



Photo P338. Feature MA\_TM\_453. Survey area to the right of the constructed berm, upland meadow with no wetland indicators. Looking SW, in Malheur County. 6/10/2013 17:30. Latitude 44.062212. Longitude -117.324042.



Photo P339. Feature MA\_TM\_456. Shovel in center of the image marks the upland verification plot, houses in the background. Looking NE, in Malheur County. 6/11/2013 7:43. Latitude 44.067678. Longitude -117.325256.





Photo P340. Feature MA\_TM\_452. Canal with narrow wetland fringe. Looking NW, in Malheur County. 6/10/2013 16:50. Latitude 44.067454. Longitude -117.325326.



Photo P341. Feature MA\_TM\_454. Irrigation canal with fringe wetland within bankful width located in the center of the image. Looking East, in Malheur County. 6/10/2013 17:41. Latitude 44.060782. Longitude -117.325825.



Photo P342. Feature MA\_TM\_036. Well vegetated upland swale with no signs of a channel. Looking West, in Malheur County. 4/29/2013 13:46. Latitude 44.058867. Longitude -117.354668.



Photo P343. Feature MA\_TM\_037. Upland swale with no signs of an active channel. Looking North, in Malheur County. 4/29/2013 14:06. Latitude 44.058775. Longitude -117.36484.





Photo P344. Feature MA\_TM\_033. Upland swale with sparse upland vegetation. Looking North, in Malheur County. 4/29/2013 11:19. Latitude 44.057348. Longitude -117.390193.



Photo P345. Feature MA\_TM\_022. Livestock disturbed upland grassland, no wetland indicators. Looking North, in Malheur County. 4/29/2013 8:15. Latitude 44.051465. Longitude -117.389768.



Photo P346. Feature MA\_TM\_023. No signs of an active channel at NHD mapped line, livestock in the background. Looking NE, in Malheur County. 4/29/2013 8:18. Latitude 44.051554. Longitude -117.390371.



Photo P347. Feature MA\_TM\_034. Swale located in the bottom of a steep depression, no signs of past flow or bed and bank development. Looking North, in Malheur County. 4/29/2013 11:49. Latitude 44.056965. Longitude -117.393635.





Photo P348. Feature MA\_TM\_030. Dry gully in sagebrush shrubland with no signs of an active channel. Looking South, in Malheur County. 4/29/2013 10:09. Latitude 44.05135. Longitude -117.414001.



Photo P349. Feature MA\_TM\_005. Small channel in the center of the image surrounded by whitetop. Looking North, in Malheur County. 4/27/2013 10:42. Latitude 44.034972. Longitude -117.480431.



Photo P350. Feature MA\_W\_0049. Narrow swale with wetland located in the bottom. Signs of livestock use visible. Looking North, in Malheur County. 8/6/2011. Latitude 44.036011. Longitude -117.480609.



Photo P351. Feature MA\_TM\_004. Vegetated upland swale with no signs of an active channel. Looking East, in Malheur County. 4/27/2013 10:21. Latitude 44.033999. Longitude -117.480376.





Photo P352. Feature MA\_TM\_003. Drainage gully adjacent to access road, no signs of an active channel. Looking North, in Malheur County. 4/27/2013 10:15. Latitude 44.031652. Longitude -117.480749.



Photo P353. Feature MA\_TM\_001. Ephemeral drainage containing a large pipe located adjacent to the access road. Looking South, in Malheur County. 4/27/2013 9:38. Latitude 44.027021. Longitude -117.477596.

Photo not available.

Photo P354. Feature MA\_S\_0182. No photo available. Looking NE, in Malheur County. 8/7/2011. Latitude 43.96299. Longitude -117.472052.



Photo P355. Feature MA\_W\_0103. Canal bank, no wetland indicators. Looking West, in Malheur County. 8/7/2011. Latitude 43.964768. Longitude -117.460751.





Photo P356. Feature MA\_W\_0091. Canal bank looking out at valley below road. No wetland indicators on roadbed. Looking South, in Malheur County. 8/7/2011. Latitude 43.964598. Longitude -117.463602.



Photo P357. Feature MA\_W\_0092. Upland ravine with river in the valley below. Looking South, in Malheur County. 8/7/2011. Latitude 43.964604. Longitude -117.464553.



Photo P362. Feature MA\_S\_0128. Sagebrush dominated depression with no signs of a channel. Looking North, in Malheur County. 8/17/2011. Latitude 43.924714. Longitude -117.456285.



Photo P363. Feature MA\_S\_0144. Livestock trail at the base of a slope, no signs of a channel. Looking East, in Malheur County. 8/17/2011. Latitude 43.911667. Longitude -117.446756.





Photo P364. Feature MA\_S\_0078. Vegetated depression in a broad valley, thistle visible throughout, no signs of a channel. Looking SW, in Malheur County. 7/25/2011. Latitude 43.850278. Longitude -117.276738.



Photo P365. Feature MApro\_397. Dry valley with fence line visible in center of image. Looking South, in Malheur County. 7/31/2012 8:37. Latitude 43.835499. Longitude -117.263293.



Photo P366. Feature Malpro\_631. Biologist holding shovel to the left of the image with road to the right. Looking West, in Malheur County. 7/31/2012 9:52. Latitude 43.791246. Longitude -117.245943.



Photo P368. Feature MA\_S\_0097. Upland valley with no signs of an active channel. Looking North, in Malheur County. 7/25/2011. Latitude 43.692461. Longitude -117.133495.





Photo P369. Feature MA\_S\_0186. Upland swale in the center of the image, view of the valley. Looking North, in Malheur County. 7/24/2011. Latitude 43.669045. Longitude -117.12302.



Photo P370. Feature MA\_S\_0148. Broad valley with no signs of an active channel. Looking West, in Malheur County. 7/22/2011. Latitude 43.631602. Longitude -117.101459.



Photo P371. Feature MA\_S\_0032. Upland valley with no signs of an active channel. Looking West, in Malheur County. 7/22/2011. Latitude 43.631114. Longitude -117.098012.



Photo P373. Feature MAPro\_435. Irrigation canal with flow control structure in the center of the image. Looking East, in Malheur County. 7/28/2012 12:20. Latitude 43.586434. Longitude -117.076679.





Photo P374. Feature MApro\_437. Bankfull irrigation canal in the center of the image. Looking NE, in Malheur County. 7/28/2012 14:38. Latitude 43.586088. Longitude -117.073656.



Photo P375. Feature MA\_W\_0111. Stream to the right of the image with a steep cut bank, no wetland indicators. Looking SW, in Malheur County. 7/21/2011. Latitude 43.58832. Longitude -117.068044.



Photo P376. Feature MApro\_446. Irrigation canal with fringe wetland, biologist in the background. Looking East, in Malheur County. 7/27/2012 11:49. Latitude 43.562297. Longitude -117.050256.



Photo P378. Feature MA\_S\_0045. Sagebrush dominated swale in the center of the image, no signs of an active channel. Looking North, in Malheur County. 7/20/2011. Latitude 43.559166. Longitude -117.034679.



This page intentionally left blank