SEISMIC PROTECTION DEVICES STUDY – MARQUAM BRIDGE

Final Report

Experimental Features 93-03





SEISMIC PROTECTION DEVICES STUDY

FOR THE

W. MARQUAM INTERCHANGE – MARQUAM BRIDGE SECTION

Experimental Features Project 93-03

by

Andrew Griffith, P.E. Oregon Department of Transportation Research Group

Wayne Normand Oregon Department of Transportation Region 1

and

Steve Starkey, P.E. Oregon Department of Transportation Bridge Section

for

Oregon Department of Transportation Research Group Salem OR 97301-5192

and

Federal Highway Administration Washington D.C. 20590

April 2000

Technical Report Documentation Page

1.	Report No.	2. Gover	nment Accession No.	3. Recipient's Catalog No.
	OR-EF-00-13			
4.	Title and Subtitle			5. Report Date
	SEISMIC PROTECTION DEV			April 2000
	MARQUAM INTERCHANGE	–MARQU	AM BRIDGE SECTION	6. Performing Organization Code
7.	Author(s)			8. Performing Organization Report
	Andrew Griffith, P.E.			No.
	Wayne Normand			
	Steve Starkey, P. E.			
9.	Performing Organization Name an	d Address		10. Work Unit No. (TRAIS)
	Oregon Department of Transportat	ion		
	Research Group			11. Contract or Grant No.
	200 Hawthorne SE, Suite B-240			SRF 306: OR93-03
	Salem, Oregon 97301-5192			
12.	Sponsoring Agency Name and Ado	dress		13. Type of Report & Period Covered
	Oregon Department of Transportat	ion	Federal Highway Administration	Construction Report
	Research Group	and	Department of Transportation	1995-2000
	200 Hawthorne SE, Suite B-240 Salem, Oregon 97301-5192		Washington, D.C.	14. Sponsoring Agency Code
15	Supplementary Notes			

13. Supplementary 140to

16. Abstract

This report summarizes the seismic retrofit of the Marquam Bridge in Portland, Oregon with proprietary bearing/restraint and shock transmission devices. The retrofit was completed in 1995. The devices were supplied by FIP Industries, Inc. and included:

- Bearing Restraint Devices (including shock transmission components); four devices at Piers #2 and #5;
- Bearing Restraint Devices: four devices at Piers #3 and #4; and
- Shock Transmission Devices: two on each side of Panel Point L13.

The bearing/restraint devices replaced existing bearings and required special modifications to the bridge piers and truss to accommodate jacking operations and bearing installation. After the installation was complete in 1995, Teflon shavings were discovered in the guide bar region in each of the new bearings on Pier #2 and Pier #5. The shavings were the result of the Teflon sliding element being extruded into the guide bar region. Since then, further monitoring has confirmed that the Teflon extrusion process has diminished over time. After almost five years of service, the other devices are performing satisfactorily.

17. Key Words	18. Distribution Statement		
SEISMIC RETROFIT, BEARING/RES MARQUAM BRIDGE, OREGON	Available through the Oregon Department of Transportation Research Group		
19. Security Classif. Unclassified	assified	20. No. of Pages	22. Price
Unclassified		23	

Technical Report Form DOT F 1700.7 (8-72)

Reproduction of completed page authorized

SI* (MODERN METRIC) CONVERSION FACTORS APPROXIMATE CONVERSIONS TO SI UNITS APPROXIMATE CONVERSIONS FROM SI UNITS Symbol When You Know Symbol Symbol When You Know To Find Symbol Multiply By To Find Multiply By LENGTH LENGTH in inches 25.4 millimeters mm millimeters 0.039 inches in mm ft 0.305 3.28 ft feet meters m m meters feet 0.914 1.09 yd vards meters yards yd meters m m 1.61 0.621 mi miles kilometers km km kilometers miles mi **AREA AREA** in^2 645.2 mm^2 mm^2 0.0016 in^2 square inches millimeters squared millimeters squared square inches ft^2 m^2 m^2 ft^2 square feet 0.093 meters squared meters squared 10.764 square feet m^2 yd^2 2.47 square yards 0.836 meters squared ha hectares acres ac mi^2 km^2 0.405 hectares ha kilometers squared 0.386 square miles ac acres mi^2 km^2 square miles 2.59 kilometers squared **VOLUME VOLUME** milliliters 0.034 fluid ounces fl oz mL milliliters L fl oz fluid ounces 29.57 mL liters 0.264 gallons gal ft^3 m^3 gallons 3.785 liters L meters cubed 35.315 cubic feet gal ft^3 m^3 m^3 vd^3 cubic feet 0.028 meters cubed meters cubed 1.308 cubic yards m^3 yd^3 cubic yards 0.765 MASS meters cubed NOTE: Volumes greater than 1000 L shall be shown in m³. 0.035 grams ounces oz kilograms 2.205 lb **MASS** kg pounds 28.35 1.102 short tons (2000 lb) T Mg oz ounces grams megagrams g lb 0.454 kg TEMPERATURE (exact) pounds kilograms T short tons (2000 lb) 0.907 megagrams Mg °C Celsius temperature 1.8 + 32Fahrenheit ٥F TEMPERATURE (exact) Fahrenheit 5(F-32)/9 Celsius temperature ٥F °C. temperature (4-7-94 jbp) * SI is the symbol for the International System of Measurement

ACKNOWLEDGEMENTS

The authors would like to thank the following people for their assistance in the preparation of this report:

Dennis Carlson, Oregon Department of Transportation Region 1 Bridge Inspection Crew Joni Reid, Oregon Department of Transportation Research Group

DISCLAIMER

This document is disseminated under the sponsorship of the Oregon Department of Transportation and the United States Department of Transportation in the interest of information exchange. The State of Oregon and the United States Government assume no liability of its contents or use thereof.

The contents of this report reflect the views of the authors who are solely responsible for the facts and accuracy of the material presented. The contents do not necessarily reflect the official views of the Oregon Department of Transportation or the United States Department of Transportation.

The State of Oregon and the United States Government do not endorse products of manufacturers. Trademarks or manufacturers' names appear herein only because they are considered essential to the object of this document.

This report does not constitute a standard, specification, or regulation.

SEISMIC PROTECTION DEVICES STUDY

TABLE OF CONTENTS

2.0	RETROFIT PLAN	5
3.0	CONSTRUCTION	9
3	.1 Contract Information	9
3	.2 VEP 1400/280-ST INSTALLATION AT PIERS #2 AND #5	10
3	.3 VEP 5200 INSTALLATION AT PIERS #3 AND #4	13
3	.4 Shock Transmission Units	16
4.0	POST-CONSTRUCTION INSPECTION	19
5.0	CONCLUSIONS AND RECOMMENDATIONS	21
6.0	REFERENCES	23
	le 1.1: Height of the Marquam Bridge Pierse 3.1: Summary of Bearing Installation on Bridge Piers	
Tab	e 3.1: Summary of Bearing Installation on Bridge Piers	9
Tab i Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	912
Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9
Figu Figu Figu Figu Figu Figu Figu Figu	LIST OF FIGURES/PHOTOS re 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River	9

Figure 3.8: Section View Showing the Four Lifting Columns and Beam for Piers #3 and #4	. 14
Figure 3.9: Bearing Pedestal Detail at Piers #3 and #4	. 15
Figure 3.10A: Original Bearings on Pier #3	. 16
Figure 3.10B: New Bearings on Pier #4	
Figure 3.11: Shock Transmission Unit at Panel L13	
Figure 3.12: Close-up of Shock Transmission Unit	. 17

1.0 INTRODUCTION

In the 1990s, greater emphasis has been placed on seismic protection of structures in Oregon. There is geologic evidence of prior catastrophic earthquakes in the region. Most bridges in use today were not designed to withstand devastating earthquakes of similar magnitude. A recent Oregon Department of Transportation (ODOT) study, "*Prioritization of Oregon Bridges for Seismic Retrofit*" found that over half of the State's bridge inventory (3,257 bridges) lacked structural details to meet current earthquake design standards.

The Marquam Bridge (Bridge #8328), constructed in 1966, is one of Oregon's most critical transportation links. It is a major interstate (I-5) freeway system bridge (Figure 1.1) that crosses the Willamette River in Portland, Oregon. Because of its location, regional importance, and vulnerability, the Marquam Bridge was retrofitted with seismic control devices in 1995. This report describes the seismic refit and follow-up monitoring of the Marquam Bridge.




Figure 1.1: A View (looking west) of the Marquam Bridge Across the Willamette River

The Marquam Bridge main spans are steel trusses carrying two superimposed roadways for a length of 318 m (1043 ft) (Figure 1.2). The end spans measure 92 m (302 ft) and consist of trusses cantilevered 27 m (90 ft) into the middle length, providing support for the 79 m (260 ft) suspended main span. Bridge supports include Pier #2, near the east bank of the Willamette




Figure 1.2: Marquam Bridge Drawings

River, Piers #3 and #4 which are in the river, and Pier #5, close to the Willamette River's west bank. In plan view, the structure is characterized by a straight longitudinal axis.

The bridge piers are reinforced concrete configured upon a two-column transverse framework connected by two struts (Figure 1.3). The columns are spaced at 19.8 m (65.0 feet) on center. The upper section is circular with each column having a diameter of 3.7 m (12.0 feet) while the lower section's columns are elliptical. The columns are connected by means of rectangular section struts, placed one each, at the top and where the section of the columns changes from elliptical to circular.




Figure 1.3: Detail of Pier Configuration

The pier height varies. Table 1.1 provides the height of the lower section of the pier, H_e and the height of the upper columns, H_c .

Table 1.1: Height of the Marquam Bridge Piers

Pier Number	\mathbf{H}_{e}	$\mathbf{H_c}$
2	16.5 m (54.0 ft)	24.7 m (81.0 ft)
3	17.4 m (57.0 ft)	20.4 m (67.0 ft)
4	18.3 m (60.0 ft)	20.1 m (66.0 ft)
5	14.0 m (46.0 ft)	24.7 m (81.0 ft)

2.0 RETROFIT PLAN

The seismic retrofit of the Marquam Bridge attempts to achieve the following objectives:

- To attain seismic protection for superstructure pull-off in the event of seismic movements from the design event.
- To minimize future strengthening of existing structural elements.
- To maintain the existing system of service load transfer.
- To limit seismic deflection to values compatible with the existing configuration.

The retrofit involved installation of proprietary bearing/restraint devices and shock transmission devices from FIP Structural Systems, Inc. This was the first application of these devices in the United States. Since they had not been used before, the seismic protection devices were selected by ODOT as an experimental feature for research, so they could be fully evaluated during and after construction.

The bearing/restraint devices and shock transmission devices required by the contract specifications included:

- Bearing Restraint Devices (including shock transmission components): four devices at Piers #2 and #5 (two at each pier). FIP device number: **VEP 1400/280-ST** (Figure: 2.1)
- Bearing Restraint Devices: four devices at Piers #3 and #4 (two at each pier). **FIP device number: VEP 5200** (Figure 2.2).
- Shock Transmission Devices: two on each side of Panel Point L13. **FIP device number: OT 440/5.5"** (Figure 2.3).

The specifications also required the manufacturer of the devices to test them prior to installation. The devices were tested in December 1994 in Italy, in accordance with the project specifications. Dr. Andrew Whittaker of the University of California's Earthquake Engineering Research Center observed and certified the testing for compliance. Testing included the following:

- Bearing/Restraint Devices
 - > Friction Test
 - Vertical Static Load Test
 - ➤ Lateral Static Load Test
 - Simulated Dynamic Load Test
- Shock Transmission Devices
 - > Impressed Deflection Test
 - Simulated Dynamic Force Transfer Test

The test results demonstrated that the devices met the project specifications.

In addition to the bearing/restraint devices and shock transmission devices, strong-motion instrumentation was also designed for the bridge to evaluate the devices under seismic loading. The instrumentation allows a comparison between site ground response, substructure response, and superstructure response. The effectiveness of the protection devices can be determined by comparing actual response to predicted response of different portions of the structure. The seismic instrumentation was installed on the bridge by the United States Geological Survey.




Figure 2.1: Bearing Restraint Devices; Piers #2 and #5 (FIP Device Number: VEP 1400/280-ST)




Figure 2.2: Bearing Restraint Devices; Piers #3 and #4 (FIP Device Number: VEP 5200)




Figure 2.3: Shock Transmission Devices: Panel Point L13 (FIP Device Number: OT 440/5.5")

3.0 CONSTRUCTION

3.1 CONTRACT INFORMATION

The seismic retrofit work was part of an ODOT construction contract, "Marquam Bridge – West Marquam Interchange (Portland) Section." Other major work items contained in the contract included the installation of:

- Replacement diagonal bracing under the lower bridge deck;
- Safety hangars, railing and protective fencing construction, and
- Illumination and navigation lights.

The contract was let in January 1994, and awarded to Mowat Construction Company of Kirkland, Washington. In February 1994, the contractor received a Notice-to-Proceed with construction. Prior to installing the bearing restraint devices, the bridge structural system required modification to allow for lifting and support of the structure during the seismic retrofit. The first jacking operation to install bearings on Pier #5 (left) occurred on March 28, 1995. The last bearing to be installed was on Pier #3 (right), and occurred on September 26, 1995. Table 3.1 provides a summary of the bearing/restraint device installation on each of the four piers.

Table 3.1: Summary of Bearing Installation on Bridge Piers

	_	
Location	Device Type	Date Installed
Pier #5 (Left)	VEP 1400/280-ST	April 5, 1995
Pier #5 (Right)	VEP 1400/280-ST	April 26, 1995
Pier #2 (Left)	VEP 1400/280-ST	May 15, 1995
Pier #2 (Right)	VEP 1400/280-ST	June 5, 1995
Pier #3 (Left)	VEP 5200	July 5, 1995
Pier #4 Right)	VEP 5200	August 2, 1995
Pier #4 (Left)	VEP 5200	August 29, 1995
Pier #3 (Right)	VEP 5200	September 26, 1995

As mentioned earlier, the seismic protection devices were proprietary, thus the contractor was required to obtain the devices directly from the supplier, FIP Structural Systems, Inc. The prices for the devices totaled almost \$500,000 and included the following cost for each device:

• Bearing Restraint Devices (including shock transmission components); FIP device number: VEP 1400/280-ST; four devices at Piers #2 and #5 (two at each pier) at **\$46,967 each**.

- Bearing Restraint Devices; FIP device number: VEP 5200; four devices at Piers #3 and #4 (two at each pier) at \$60,967 each.
- Shock Transmission Devices; FIP device number: OT 440/5.5"; two on each side of Panel Point L13 at \$24,467 each.

The contract specifications required shop drawings for the seismic protection devices and instructions for their installation. The bearing/restraint devices and shock transmission devices were installed in accordance with the manufacturer's instructions and contract specifications. In the next three sections, the installation of the bearing/restraint devices and shock transmission devices is reviewed.

3.2 VEP 1400/280-ST INSTALLATION AT PIERS #2 AND #5

Installation of the VEP 1400/280-ST bearing/restraint devices at Piers #2 (left and right) and #5 (left and right) required that the existing base of the pier columns be modified to accommodate placement of the jacking columns. At the pier base, concrete support collars were constructed to carry the jacking pipe supports (Figure 3.1).



Figure 3.1: Collars Being Constructed Around Pier Columns

A lifting shoe for jacking the structure was constructed and bolted to the bottom of the bridge truss chord. An additional strut was attached to strengthen the structure to accommodate the jacking at the bearing connection (Figure 3.2).




Figure 3.2: Additional Strut and Lifting Shoe Assembly at Piers #2 and #5

Once the concrete support collars were built, the lifting assembly for each bearing/restraint device was constructed alongside the pier column. The lifting assembly consisted of two pipe columns (outside diameter - 863.6 mm (34.0 in)), one lifting beam, temporary bearings and four jacking devices (Figure 3.3 and Figure 3.4).



Figure 3.3: The Lifting Assembly for Piers #2 and #5




Figure 3.4: Section View Showing the Two Lifting Columns and Beam for Piers #2 and #5

Four 363 Mg (400 ton) jacks raised the lifting assembly. After the lifting assembly was in place, the structure was jacked and temporary bearings and shims were slid into place to support the structure while other modifications were accomplished. The structure was raised about 25.4 mm (1.0 in) as the loads were transferred from the old bearing onto the jack and jacking columns. The existing truss bearing was then removed.

A hydraulic crane lowered a new bearing shoe assembly from the top deck of the bridge. It was placed and bolted to the bottom of the truss chord. Fifteen 31.6 mm (1.25 in) threaded anchor rods, with two hex nuts and a 25.4 mm (1.0 in) x 150 mm (6 in) square plate at the top end of each rod, were drilled and bonded into the existing concrete. The bearing anchor plate was placed so that it was level and supported by the square plates on the anchor rods. The anchor plate was positioned with the transverse axis in line with the centerline of the bearing and the longitudinal axis aligned with the centerline of the bottom truss chord. The adjacent approach bearing device was not removed, but encapsulated in concrete as the concrete pedestal for the new bearing was constructed (Figure 3.5).

The masonry plate was set and connected to the anchor plate. After the masonry plate was set, the structure was jacked to allow for the installation of the new bearing assembly. The structure was raised about 25.4 mm (1.0 in) as the loads were transferred from the temporary bearings back onto the jacks.

The crane positioned on the top deck of the bridge lifted the new bearings from the bridge deck down the side of the bridge. The bearings were maneuvered onto the pier (Figure 3.6) and connected to the masonry plate and the sole plate of the bearing shoe assembly. Once the jacks were lowered, the bearing was operational, and carrying the live and dead loads of the structure.




Figure 3.5: New Concrete Bearing Pedestal and Encapsulated Approach Bearing Device




Figure 3.6: Bearing is Positioned between Masonry Plate and Top Sole Plate

3.3 VEP 5200 INSTALLATION AT PIERS #3 AND #4

The installation work sequence at Piers #3 (left and right) and #4 (left and right) for the VEP 5200 bearing and restraint devices was similar to the VEP 1400/280-ST bearing/restraint device installation on Piers #2 and #5. Concrete support collars were constructed at the base of the pier columns to support the jacking pipe supports. For each bearing replacement, the lifting assembly consisted of four pipe columns (863.4 mm (34.0 in) outside diameter), two lifting beams and cross braces, four temporary bearings, and eight, 726 Mg (800 ton) jacking devices (Figure 3.7 and Figure 3.8). For this installation, no additional struts were needed on the truss to support the lifting operations. Two lifting shoes were connected to the bottom of the bridge truss chord by replacing existing rivets with high-strength bolts. The lifting beams were turn bolted to the lifting shoes.



Figure 3.7: The Lifting Assembly for Piers #3 and #4




Figure 3.8: Section View Showing the Four Lifting Columns and Beam for Piers #3 and #4

After the lifting assembly was in place, the structure was jacked and temporary bearings and shims slid into place to support the edifice while the other modifications were made. To transfer loads from the old bearing onto the jacks and jacking columns, the structure was raised about 25.4 mm (1.0 in). The existing truss bearing was removed, and the new bearing shoe assembly lowered by a crane from the top deck, placed, and bolted to the bottom of the truss chord.

Next, reinforcing steel and leveling rods for the concrete pedestal were placed. Twelve 31.6 mm (1.25 inch) threaded anchor rods, with two hex nuts and one 25 mm (1 in) x 150 mm (6 in) square plate at each rod, were drilled and bonded into the existing concrete.

Subsequently, the bearing masonry plate was set and a concrete pedestal was constructed. The masonry plate was supported by the 25 mm (1 in) x 150 mm (6 in) square plates at the top end of the anchor rods. As before, the masonry plate was positioned on the leveling nuts so the transverse axis would be in line with the centerline of the new bearing and the longitudinal axis would align with the centerline of the bottom truss chord. Figure 3.9 shows the pedestal detail with anchor rods.




Figure 3.9: Bearing Pedestal Detail at Piers #3 and #4

After the concrete pedestal was constructed, the structure was jacked to allow for the installation of the new bearing assembly. The structure was raised about 25.0 mm (1.0 in) as the loads were transferred from the temporary bearings back onto the jacks. Once in position, the bearing assembly was bolted to the masonry plate, and to the bearing shoe's sole plate and the structure was lowered onto the new bearing. The new bearing/restraint device was then fully operational.

Figure 3.10 (A & B) shows a "before" picture on Pier #3 with the original bearing and a picture on pier #4 after the VEP 5200 bearing/restraint device installation.



Figure 3.10A: Original Bearings on Pier #3



Figure 3.10B: New Bearings on Pier #4

3.4 SHOCK TRANSMISSION UNITS

Shock transmission units were installed on each side of the lower deck bridge truss at panel points 13 and 21 (Figures 3.11 and 3.12). The shock transmission devices are designed to diffuse the rapidly applied loads of a seismic event. With their action, both longitudinal and

transverse seismic forces are shared by all base isolation devices in approximate proportion to substructure strengths. This minimized structure displacements and provided maximum damage protection.

Safety hangers, installed on both sides of the main span of the bridge at panel points 13 and 21, are visible in Figure 3.11. These two panel points are the locations of the expansion joints for the suspended portion of the bridge.



Figure 3.11: Shock Transmission Unit at Panel L13



Figure 3.12: Close-up of Shock Transmission Unit

4.0 POST-CONSTRUCTION INSPECTION

Shortly after the installation of the 1400/280-ST devices at Piers #2 and #5, Teflon shavings were found in the guide bar area in each of the bearings. On October 18, 1995, Dr. Rene Medeot of FIP Industries, Inc. met with ODOT representatives to jointly inspect the bearings and review the problem. Dr. Medeot attributed the shavings to Teflon sliding element extrusions into the guide bar region (*Starkey 1997*).

Dr. Medeot theorized that the Teflon was able to extrude because the rivets holding the brass restraining bars had broken. This was caused by the plastic flow of Teflon under the brass retaining strips, which produced unanticipated tension on the rivets. According to Dr. Medeot, the driving force for this action was the sustained dead loading on the bearing. He believed the rivets failed because the restrainer bars were designed for a sustained dead load of 4,005 kN (900 kips) which was about 20% less than the apparent dead load present (4,893 kN (1,100 kips)). The higher load produced Teflon plastic flow between the restrainer bar and its attachment, which in turn caused the rivet tensile force and the rivet shear force from containment.

According to Dr Medeot, the extrusion process proceeds in a logarithmically decreasing fashion, and would stabilize over time. On this advice, the contractor (Mowatt Construction Company), FIP Industries Inc., and ODOT agreed to extend the contract time for a one-year period to allow for additional monitoring. The one-year observation period ended in December 1996. The measurements showed that the overall Teflon thickness was not varying appreciably, so it was believed the extrusion process had abated. FIP Industries, Inc. also provided a five-year warranty for the bearings. The warranty ends September 26, 2000.

Recently, on January 31 2000, ODOT's contract inspector and Region 1 bridge inspector visually inspected the bearings on Pier #2. They found some Teflon shavings around each of the bearings, but it appears that the Teflon extrusion process has subsided. The amount of Teflon found indicates the problem has diminished considerably and no further action is required at this time. However, further monitoring is necessary to ensure there are no long-term affects.

There have been no problems reported with any of the bearing/restraint devices on Piers # 3 and #4. Additionally, in the most recent bridge inspection performed by ODOT's Region 1 bridge inspector in July 1998, no problems were noted associated with any of the seismic protection devices.

5.0 CONCLUSIONS AND RECOMMENDATIONS

The bearings and shock transmission units appear to be in generally good condition and suitable for the purpose intended.

All seismic protection devices should be monitored for serviceability on a continuing basis. Special attention should be given to the bearing/restraint devices on Piers # 2 and # 5 to verify that the Teflon extrusion has been curtailed. Monitoring frequency for these bearing/restraint devices (on Piers # 2 and # 5) should be yearly. The other devices should be closely inspected at the time of the regularly scheduled biennial bridge inspection.

If a seismic event occurs, the devices should be inspected for any damage, and to assess suitability for continued service load performance. The bridge's actual response should be compared to the predicted response to evaluate the effectiveness of each device.

6.0 REFERENCES

Oregon Department of Transportation. *Prioritization of Oregon Bridges for Seismic Retrofit.* Final Report. January 1997.

Oregon Department of Transportation. *Bridge Inspection Report – Willamette River Marquam Bridge*. July 17, 1998.

Starkey, Steve. *ODOT Construction Completion Inspection Report*. Oregon Department of Transportation. June 28, 1997.