DEQ - Hazardous Waste Program Annual Hazardous Waste Report Source Code Group

Source codes describe the type of process or activity (i.e., source) from which a hazardous waste was generated. Review the groups and pick the appropriate code for use on the Generation & Management (GM) forms.

	Wastes from Ongoing Production and Service Processes (waste from general day to day manufacturing, production, or maintenance activities)
Code	Source Code Description
G01	Dip, flush or spray rinsing (using solvents to clean or prepare parts or assemblies for further processing - i.e., painting or assembly)
G02	Stripping and acid or caustic cleaning (using caustics to remove coatings or layers from parts or assemblies)
G03	Plating and phosphating (electro- or non-electroplating or phosphating)
G04	Etching (using caustics or other methods to remove layers or partial layers)
G05	Metal forming and treatment (pickling, heat treating, punching, bending, annealing, grinding, hardening, etc.)
G06	Painting and coating (manufacturing, building, or maintenance)
G07	Product and by-product processing (direct flow of wastes from chemical manufacturing or processing, etc.)
G08	Removal of spent process liquids or catalysts (bulk removal of wastes from chemical manufacturing or processing, etc.)
G09	Other production or service-related processes from which the waste is a direct outflow or result (specify in comments)
	Wastes From Other Intermittent Events or Processes
Code	Source Code Description
G11	Discarding off-specification, out-of-date, and/or unused chemicals or products
G12	Lagoon or sediment dragout and leachate collection (large scale operations in open pits, ponds, or lagoons)
G13	Cleaning out process equipment (periodic sludge or residual removal from enclosed processes including internal scrubbing or cleaning)
G14	Removal of tank sludge, sediments, or slag (periodic sludge or residual removal from storage tanks including internal scrubbing or cleaning)
G15	Process equipment change-out or discontinuation of equipment use (final materials and residuals removal including cleaning)
G16	Oil changes and filter or battery replacement (automotive, machinery, etc.)
G17	Subpart K laboratory waste clean-out (Generator must opt-in to Subpart K)
G19	Other one-time or intermittent processes (specify in comments)
	Residuals From Pollution Control and Waste Management Processes
Code	Source Code Description
G21	Air pollution control devices (e.g., baghouse dust ash, etc. from stack scrubbers or precipitators; vapor collection, etc.)
G22	Laboratory analytical wastes (e.g., used chemicals from laboratory operations)



State of Oregon Department of Environmental Quality Hazardous Waste 700 NE Multnomah St. Suite 600 Portland, OR 97232 Phone: 503-229-6968 800-452-4011 www.oregon.gov/DEQ

G23	Wastewater treatment (e.g., sludge, filter cake, etc., including wastes from treatment before discharge by NPDES or POTW or by UIC disposal)
G24	Solvent or product distillation as part of a production process (including totally enclosed treatment systems). Does not include batch treatment in a separate process.
G25	Treatment, disposal, or recycling of hazardous wastes – indicate in Item A-5a, on the GM form, the management method code (the related H code, but not H141) that produced the residuals.
G26	Leachate collection (from landfill operations or other land units)
G27	Treatment or recovery of universal waste
	Wastes From Spills and Accidental Releases
Code	Source Code Description
G31	Accidental contamination of products, materials, or containers (other than G11)
G32	Cleanup of spill residues (infrequent, not routine)
G33	Leak collection and floor sweeping (ongoing, routine)
G39	Other cleanup of current contamination (specify in comments)
	Wastes From Remediation of Past Contamination
Code	Source Code Description
G41	Closure of hazardous waste management unit under RCRA
G42	Corrective action at a solid waste management unit under RCRA
G43	Remedial action or emergency response under Superfund
G44	Cleanup under State or voluntary program
G45	Cleanup of underground storage tank
G46	Investigation Derived Waste approved & overseen by DEQ or EPA
G49	Other remediation (specify in comments)
	Wastes Received by an LQG from VSQGs Under the Control of the Same Person
G51	Hazardous wastes received by an LQG from VSQGs under the control of the same person
	Wastes Not Physically Generated On-Site
Code	Source Code Description
G61	Received from off-site for storage/bulking and transfer off-site for treatment or disposal (to match H141 received waste quantities from Form WR's). GENERATION QUANTITY SHOULD BE ZERO to avoid double counting.
G62	Hazardous waste received from a site located outside of U.S. states, territories, or protectorates - report a country code. This site was the generator of record and is the U.S. Importer.
G76	Evaluated hazardous waste pharmaceuticals accumulated by a reverse distributor
G77	Airbag waste received from airbag waste handlers exempted under 40 CFR 261.7(j) prior to arrival at the airbag collection facility or designated facility