

**Blue Text** indicates PW sets

**Bold Black Text** indicates document

names

### **Milestone Process**

### **Project Initiation to PSnE**

Note 1:

ProjectWise sets are a way to allow others access to files in multiple discipline folders without having to navigate to multiple folders. When placed in a set, links to the original documents within their discipline folder allows access to these files without needing to move them to a new location. This avoids duplication of files, and allows files to remain with the appropriate discipline throughout the lifecycle of a project. Allows for the final tracking of legally signed documents that are part of the bids and contract. This workflow attempts to minimizes the number of sets passed on and the number of times a files needs to be added to set.

Note 2:

For the purposes of this document, PE Lead consists of Transportation Project Manager or Resident Engineer – Consultant, assigned to project.

Legend

Orange Boxes correspond to PE Lead tasks


Green Boxes correspond to Region Rep tasks

Blue Boxes correspond to Area Manager and Tech Center Manager tasks

Purple Boxes correspond with Region Specification Writer tasks

Tan Boxes correspond with Project Delivery Quality Assurance Engineer (PDQAE) tasks

#### **PROJECT INITIATION PHASE**



RMS System Admin baselines project. Changes K####\_PI\_Set attributes to Baselined.

# DRAFT DESIGN ACCEPTANCE PHASE

1\_Design
0\_Temp
0\_Temp
0\_Project\_Initiation
0\_Project\_DAP
0\_2\_DAP
0\_3\_Preliminary
0\_4\_Advance
0\_5\_Final

☑ 6\_PSnE

💯 7\_3D\_Design

folder: K#####\_DAP\_Set

PE Lead prepares DAP Review Set in 2\_DAP

Certification of Design Acceptance with DAP Checklist
DAP Narrative
DAP Exception Request (if applicable)
Supporting documents as required

 ${\sf PE}\ {\sf Lead}\ {\sf changes}\ {\sf state}\ {\sf of}\ {\sf Set}\ {\sf to}\ {\sf FINAL-Send}\ {\sf Link}\ {\sf for}\ {\it K\#\#\#\#\_DAP\_Set}\ {\sf to}\ {\sf Tech}\ {\sf Center}\ {\sf Manager}\ {\sf to}\ {\sf Review}$ 

Area Manager, Tech Center Manager and Project Team discuss issues, prepare a plan to resolve.

Tech Center Manager Reviews K######\_DAP\_Set for completeness.

Determines project readiness.

State Project Delivery Branch Concurrence/Non-Concurrence

DAP Certification is Signed and Approved by all signatories.

YES

Region Manager for approval.

Area Manager, Tech Center Manager prepare DAP Exception Letter detailing dates and resolution plan. Forward to

PCO Pre-Letting Specialist Forwards DAP Exception letter to Statewide Project Delivery Branch Manager for Concurrence Process

After Design Acceptance/DAP Exception Letter concurrence, final comments/edits are addressed in working files located in discipline folders. PE Lead ensures Region Reps/Consultant Reps have addressed all comments/edits. Create new K##### DAP\_Set\_02 in 2\_DAP folder

K#####\_DAP\_SET files state changed to FINAL. PE Lead notifies PDQAE files are ready for review.

\*use managed export/ import workflow to change document KHAHAA DAP Set or files state changed to FINAL. PE Lead notifies PDQAE files are ready for review.

PDQAE performs review of K#####\_DAP\_Set. Provide Comments to project team

Region Discipline Reps/Consultant Reps respond to all assigned comments in comment log and working files located in discipline folders.

Electronic Redlines or scanned redlines are placed in

3\_Preliminary

**Preliminary Design Phase** 



Bold Blue text: indicates PW sets Bold black text:

## Milestone Process

Project Initiation to PSnE

Continued from Page 1

Region Discipline Reps/Consultant Reps respond to all assigned comments

in comment log and working files located in discipline folders.

**Advance Plans Phase** 

### Preliminary Design Phase

Area Manager and Tech Center Manager tasks Purple Boxes correspond

Blue Boxes correspond to


Legend

Orange Boxes correspond to PE Lead tasks

Green Boxes correspond to Region Rep tasks


Purple Boxes correspond with Region Specification Writer tasks

Tan Boxes correspond with Project Delivery Quality Assurance Engineer tasks



K#####\_Preliminary\_SET state changed to

\*final status on sets secures the files from being removed from the set or deleted.





Bold Blue text: indicates PW sets Bold black text: indicates document names Bold Purple text:

indicates added documents

**Milestone Process** 

Project Initiation to PSnE

Continued from Page 3

**Final Plans Phase** PE Lead (PL, CPM, LAL, or LCE) Pdf of deliverables placed in 5\_Final folder. Add to K####\_Final\_Set. □ Design U 0\_Temp □ 1\_Milestone\_Submissions D 0\_Project\_Initiation 1\_Draft\_DAP Specifications and PreCon Estimate are DAP updated. Construction Schedule is adjusted. 3\_Preliminary Estimate (no prices) is updated. All added to 5\_Final folder. Add to K####\_Final\_Set 4\_Advance 5\_Final D 6\_PSnE 7\_3D\_Design K####\_Final\_Set Narrative Plans (all sheets in one pdf) TMZ **Decision Tree** Estimate (no prices) **Specifications Construction Schedule** Other Project-Specific Documents as required **Original Comment Log** PE Lead creates distribution letter. Send to Project Team/Reviewers with set link. Reviewers place comments into Comment Log. Electronic Redlines or scanned redlines are placed in 5\_Final folder Region Discipline Reps/Consultant Reps respond to all assigned comments in comment log. Future "workflow" change state on Deliverable Documents set to "Final" documents-FinalStatus by PE Lead documents set to Final Status by PE Lead

**PSnE** 

Orange Boxes correspond to PE Lead tasks

Green Boxes correspond to Region Rep tasks

Legend

Blue Boxes correspond to Area Manager and Tech Center Manager tasks

Purple Boxes correspond
with Region Specification
Writer tasks
Tan Boxes correspond
with Project Delivery
Quality Assurance
Engineer tasks