

Table of Contents

| | |
|--|----|
| Table of Contents | i |
| Table of Figures | v |
| Introduction..... | 3 |
| HCRH Significance | 3 |
| Vision for HCRH | 4 |
| Purpose of Master Plan Update | 4 |
| Summary of Major Recommendations..... | 4 |
| Priority Recommendations and Cost Estimates | 5 |
| Implementation Strategy | 6 |
| HCRH History | 9 |
| Genesis | 11 |
| Key Individuals..... | 12 |
| Design Approach..... | 12 |
| Roadway, Bridge and Other Design Elements..... | 14 |
| Losses over Time..... | 18 |
| Current Conditions | 26 |
| Related Plans | 26 |
| Historic Columbia River Highway Advisory Committee..... | 19 |
| Partnering | 19 |
| HCRH Segments | 21 |
| Recommendations for All Sections..... | 23 |
| Section 1–Sandy River to Warrendale..... | 24 |
| Vision..... | 24 |
| a) Sandy River Bridge to the Springdale | 25 |
| b) Springdale | 25 |
| c) Rural | 25 |
| d) Corbett..... | 26 |
| e) Rural | 26 |
| f) Portland Women’s Forum to Larch Mountain Junction | 26 |
| g) Larch Mountain Junction to Bridal Veil Junction | 27 |

| | |
|--|-----------|
| h) Bridal Veil Junction to Western end of West Multnomah Falls Viaduct | 28 |
| i) Multnomah Falls (including viaducts)..... | 30 |
| j) East of eastern Viaduct to Dodson Interchange..... | 32 |
| k) Frontage Road | 32 |
| Section 2—Warrendale to Mosier | 35 |
| Vision..... | 35 |
| a) Warrendale to Moffett Creek..... | 36 |
| b) Moffett Creek to Cascade Locks | 36 |
| c) WaNaPa Street | 39 |
| d) Forest Lane | 39 |
| e) Frontage Road | 39 |
| f) Herman Creek to Wyeth..... | 39 |
| g) Wyeth to Starvation Creek..... | 40 |
| h) Starvation Creek to Viento..... | 40 |
| i) Viento to Mitchell Point..... | 40 |
| j) Mitchell Point..... | 41 |
| k) Mitchell Point to Hood River | 42 |
| l) Westcliff Drive..... | 43 |
| m) Cascade Avenue | 43 |
| n) Oak Street, Second Street and State Street | 44 |
| o) Hood River to Senator Mark O. Hatfield West Trailhead | 44 |
| p) Trailhead to Trailhead..... | 45 |
| q) Trailhead to Mosier..... | 46 |
| Section 3—Mosier to The Dalles | 50 |
| Vision..... | 50 |
| a) Mosier | 51 |
| b) Orchards | 51 |
| c) Plateau Mayerdale—Rowena Crest..... | 51 |
| d) Loops—Rowena Crest to Rowena Ferry Road..... | 51 |
| e) Rowena | 52 |
| f) Rowena to Chenoweth Creek | 52 |
| Proposed Management Activities..... | 53 |
| Collaboration with Others | 55 |
| Cultural Resource Management | 55 |
| Traffic Management..... | 56 |
| Actions to be Taken on All Sections | 59 |
| Last Resort Techniques..... | 60 |
| Techniques Eliminated | 60 |

Recreational Resources 62

Scenic Resources Management 64

Vista Enhancement and View Management 65

Adopted Policies 67

 Monument Policy 67

Design Guidelines 68

 1924 Log 68

 Columbia River Gorge National Scenic Area Design Guidelines 68

 Graphic Signing System 68

 Family of Railing Designs 69

 Pedestrian Railing 69

Interpretation 70

Progress on Restoration and Reuse of the HCRH—1987–2005 71

 Historic Columbia River Highway 73

 Designations 73

 Promotion of the HCRH 73

 Documentation of the HCRH 75

 Mile Posts 76

 Guardrail 76

 Interpretive Signs 77

 Thematic Signing 78

 Angel’s Rest Trailhead 79

 Elowah Falls Trailhead 79

 West Oneonta Trailhead 79

 Vista House Restoration 79

 Rowena Crest and Gravel Pit Restoration 80

 Toothrock Tunnel Lighting 81

 Planned and Funded Projects 81

 Historic Columbia River Highway State Trail 82

 Tanner Creek To Eagle Creek 82

 Hood River to Mosier 84

 Moffett Creek to Tanner Creek 89

 Eagle Creek to Cascade Locks 91

 Starvation Creek to Viento 92

Plans for Funding Future Projects on the HCRH 93

 Funding Priorities 95

 Funding Sources 95

 Action Plan 97

| | |
|---|-----|
| Remaining Issues | 101 |
| HCRH Signing Plan..... | 103 |
| Job Corps Turn | 104 |
| Button Junction | 104 |
| Shooting Range Pit | 104 |
| Mosier Pit | 104 |
| Noxious Weed Control | 104 |
| Ongoing Maintenance..... | 104 |
| Larch Mountain Slide..... | 105 |
| Ownership of HCRH..... | 105 |
| Perceived Conflict Between Cultural Resource and Visual Resource Requirements | 105 |
| Theme for Springdale | 105 |
| Parking along the Sandy River | 105 |
| Casino | 105 |
| Appendices..... | 107 |
| Appendix 1 — Excerpts from HCRH National Register Nomination | 109 |
| Appendix 2 — Excerpts from HCRH National Historic Landmark Nomination | 123 |
| Appendix 3 — HCRH Legislation | 135 |
| Appendix 4 — Columbia River Gorge National Scenic Area Act—Excerpt..... | 141 |
| Appendix 5 — Excerpts from CRGNSA <i>Management Plan</i> | 145 |
| Appendix 6 — <i>National Scenic Byway Corridor Management Plan</i> Excerpts | 189 |
| Appendix 7 — HCRH Framework Memorandum of Understanding | 211 |
| Appendix 8 — HCRH Connection Project Operation and Maintenance Memorandum of Agreement | 221 |
| Appendix 9 — Hood River to Mosier Memorandum of Agreement | 233 |
| Appendix 10 — Cascade Locks Programmatic Agreement..... | 245 |
| Appendix 11 — Appendix 10—Cascade Locks Programmatic Agreement | 257 |
| Appendix 12 — Mosier Programmatic Agreement..... | 269 |
| Appendix 13 — Access Policy | 281 |
| Appendix 14 — Monument Policy | 295 |
| Appendix 15 — Historic American Engineering Record Drawings..... | 305 |
| Appendix 16 — HCRH Interpretive Signs and Posters | 335 |
| Appendix 17 — Historic Columbia River Highway Awards | 397 |
| Appendix 18 — Before and After Photos | 401 |
| Appendix 19 — Family of Railing Designs | 427 |
| Appendix 20 — Antique Vehicle Events Information | 437 |
| Appendix 21 — Corbett Area Plan..... | 443 |
| Appendix 22 — HCRH Advisory Committee Members | 467 |
| Appendix 23 — List of Potentially Historic Sites from 1981 Study | 475 |

Table of Figures

| | |
|---|----|
| Figure 1 — Historic Columbia River Highway Keystone Sign..... | 3 |
| Figure 2 — HCRH Vision Poster..... | 7 |
| Figure 3 — Original HCRH Poster | 13 |
| Figure 4 — Recent Past Poster..... | 15 |
| Figure 5 — Columbia River Gorge National Scenic Area Management Plan | 16 |
| Figure 6 — Current Condition Poster..... | 17 |
| Figure 7 — View from the Past—Crown Point, Vista House and the HCRH..... | 20 |
| Figure 8 — Sandy River Bridges..... | 24 |
| Figure 9 — View of Crown Point and Vista House from Portland Women’s Forum State Scenic Viewpoint..... | 26 |
| Figure 10 — Crown Point Viaduct and Vista House..... | 27 |
| Figure 11 — Crown Point, 1914 | 28 |
| Figure 12 — Latourell Bridge looking Southeast towards Falls Chalet..... | 28 |
| Figure 13 — Shepperds Dell Falls..... | 29 |
| Figure 14 — Wahkeena Falls | 29 |
| Figure 15 — Wahkeena Falls Footbridge | 30 |
| Figure 16 — Multnomah Falls, Benson Footbridge and Multnomah Creek Bridge | 30 |
| Figure 17 — Multnomah Falls Site Plan | 31 |
| Figure 18 — Oneonta Tunnel | 32 |
| Figure 19 — Horsetail Falls | 33 |
| Figure 20 — Water Fountain near Ainsworth State Park..... | 33 |
| Figure 21 — Visual Simulation of HCRH State Trail at McCord Creek | 35 |
| Figure 22 — Toothrock Viaduct..... | 37 |
| Figure 23 — Toothrock Tunnel Bridge | 37 |
| Figure 24 — Eagle Creek Bridge..... | 38 |
| Figure 25 — HCRH State Trail Undercrossing Interstate 84 Between Eagle Creek and Cascade Locks..... | 38 |
| Figure 26 — Bridge of the Gods featuring the Cascade Locks Mural..... | 39 |
| Figure 27 — Moss covers the Original Highway Surface near Lindsey Creek..... | 40 |
| Figure 28 — Mitchell Point Tunnel—The Tunnel of Many Vistas..... | 41 |
| Figure 29 — Ruthton Point Before and After Restoration..... | 42 |
| Figure 30 — Proposed Enhancements for Westcliff Drive..... | 43 |

Figure 31 — Pedestrian Railing in Hood River44

Figure 32 — Hood River Loops44

Figure 33 — Evolution of West Portal of West Mosier Twin Tunnel45

Figure 34 — Restored Rubble Masonry Parapet Wall and Guardrail46

Figure 35 — New Overlook East of the Mosier Twin Tunnels is often called the Ellipse ...46

Figure 36 — Typical Section for WaNaPa47

Figure 37 — Cross Section for WaNaPa and Forest Lane47

Figure 38 — View of the Original Hood River Bridge.....48

Figure 39 — Cross-Section for Cascade Avenue.....49

Figure 40 — Orchards East of Mosier.....50

Figure 41 — View to East from Rowena Crest51

Figure 42 — Restoration Partnership receiving National Trust for Historic
Preservation Honor Award55

Figure 43 — Historic Photo of the Multnomah Falls Viaduct57

Figure 44 — Original Concrete Mile Post58

Figure 45 — Bicycling on the Historic Columbia River Highway near Bridal Veil59

Figure 46 — Antique Cars at 2000 Celebration61

Figure 47 — Cycle Oregon Riders at the Ellipse62

Figure 48 — Tourists at Multnomah Falls.....63

Figure 49 — The Corridor Visual Inventory proposes Enhancements along the HCRH.....65

Figure 50 — Horsetail Falls66

Figure 51 — Samuel Lancaster Commemoration Plaque.....67

Figure 52 — Plaque commemorating Construction of the Columbia River Highway.....67

Figure 53 — The “Columbia River Gorge National Scenic Area Design Guidelines”68

Figure 54 — Pedestrian Railing Design.....69

Figure 55 — Interpretive Sign at Ruckel Creek.....70

Figure 56 — Multnomah Falls73

Figure 57 — 75th Anniversary of the HCRH74

Figure 58 — Celebration 2000 Antique Car Parade74

Figure 59 — Troutdale All-American Road Celebration.....75

Figure 60 — Historic Mile Posts.....76

Figure 61 — Two-Rail, Steel-Backed, Wooden Guardrail.....76

Figure 62 — Interpretive Sign at Bridal Veil State Park77

Figure 63 — Interpretive Sign at Portland Women’s Forum77

Figure 64 — Interpretive Sign at Eagle Creek Overlook.....77

Figure 65 — Toothrock Trailhead Site Sign78

Figure 66 — Entering Columbia River Gorge National Scenic Area Sign.....78

Figure 67 — The Thematic Site Sign at Vista House used the existing Stone Base
and the Thematic Sign Shape and Colors78

Figure 68 — Ainsworth State Park Thematic Site Sign78

Figure 69 — Angel’s Rest Trailhead at Bridal Veil Junction79

Figure 70 — Kiosk at Angel’s Rest Trailhead79

Figure 71 — Elowah Falls Trailhead79

Figure 72 — West Oneonta Trailhead79

Figure 73 — Vista House Restoration.....80

Figure 74 — Rowena Pit before Restoration.....80

Figure 75 — Simulation of Restoration of Rowena Pit80

Figure 76 — Toothrock Tunnel as It appeared when first Lit.....81

Figure 77 — Deterioration at the Crown Point Viaduct81

Figure 78— Toothrock Viaduct Railing deteriorated Condition.....82

Figure 79 — Toothrock Viaduct Railing Repaired82

Figure 80 — Damaged Eagle Creek Viaduct83

Figure 81 — Eagle Creek Viaduct Repaired.....83

Figure 82 — Toothrock Tunnel Bridge83

Figure 83 — Groove included on Stairway allows for Bike Access.....83

Figure 84 — 1920s Photo of West Portal of Mosier Twin Tunnels.....84

Figure 85 — 1987 Photo of West Portal of Mosier Twin Tunnels84

Figure 86 — Leon Kinner’s Model A Roadster in Mosier Twin Tunnels in 199685

Figure 87 — Senator Mark O. Hatfield at East Trailhead during Dedication 199685

Figure 88 — Rockfall Catchment85

Figure 89 — Rockfall Catchment from Above86

Figure 90 — Senator Mark O. Hatfield West Trailhead86

Figure 91 — Opening Day 2000 at the Twin Tunnels Visitor Station87

Figure 92 — Twin Tunnels Visitor Station87

Figure 93 — Newly constructed Guardrail.....87

Figure 94 — Rock Wall repaired near Inspiration Point88

Figure 95 — Hanel Quarry Overflow Parking in the Process of Construction.....88

Figure 96 — A New Overlook with Outstanding View88

Figure 97 — East Pit Restoration in Progress88

Figure 98 — Millennium Legacy Trail Art—Pine Cones89

Figure 99 — Millennium Legacy Trail Art—Seating.....89

Figure 100 — Geoweb Retaining Wall supports a Wide Variety of Vegetation89

Figure 101 — Switchback.....89

Figure 102 — Tanner Creek Bridge Railing Repaired90

Figure 103 — Moffett Creek Bridge Railing was replaced to match the Original90

Figure 104 — Caps on Street Signs90

Figure 105 — Interstate 84 Undercrossing91

Figure 106 — Rockery Retaining Wall91

Figure 107 — Rockfall Mitigation between Starvation Creek and Viento92

Figure 108 — Trail to Starvation Creek Waterfall.....92

Figure 109 — Starvation Creek Trailhead.....92

Figure 110 — Rockfall Catchment Structure during Construction95

Figure 111 — Funding Priorities Table.....96

Figure 112 — Mitchell Point Viewpoint97

Figure 113 — Locations of Proposed Projects 98-99

Figure 114 — Funding Sources Table 98-99

Figure 115 — Proposed Historic US 30 Sign.....103